


# 2 AXIS PORTABLE MILLING MACHINE

ILLUSTRATION SHOWS THE MIRAGE MR2000-A



## COMMON METHODS FOR MOUNTING A PORTABLE MILLING MACHINE

- Mounting plates and brackets
- Chain clamp
- Gantry
- Switch magnets
- Heat exchanger mounting brackets
- Ratchet straps

For full details of portable machines for on-site machining projects visit the website

[www.miragemachines.com](http://www.miragemachines.com)

**MIRAGE**  
PORTABLE PERFORMANCE